




Introduction to 3D Parametric CAD Modeling

Sketch Environment

- Usually only 2D geometry
- 2D sections are used to define sketched features































































Introduction to 3D Parametric CAD Modeling

Assembly Environment

- Parts are used to create sub-assemblies.
- Sub-assemblies are used to define larger assemblies.
- Assemblies can be used in other assemblies or drawing files.






















Introduction to 3D Parametric CAD Modeling











SECTION A-A SCALE 1:1









